



Montana Department of Transportation



*Appendix G*  
*Forest Service Bridge Report*

Structure Name: Timberlane  
 Route & MP: 68-07.4

Inspection Date: 8/12/05

**USDA, FOREST SERVICE  
 ROUTINE ROAD BRIDGE INSPECTION REPORT**

<b>IDENTIFICATION and LOCATION:</b>			
Structure Name:	Timberlane		
Route:	68	Milepost:	07.4
Forest:	Kootenai National Forest	District:	Libby
Feature Crossed:	Pipe Creek		

<b>BRIDGE RATING SUMMARY:</b>			
Date:	8/12/05	Time Started:	12:30 PM
		Time Completed:	1:45 PM
Inspection Team:	K. Yakawich / M. Yakawich		
Weather:	Rain 65°		
Rerating required based on current inspection?	Organization: Great West Engineering		
YES	<input checked="" type="radio"/> NO	(Circle One)	
		Insp Team	
		Leader:	
			Signature
		Ind. In Charge	
			Signature

**RECOMMENDED WORK**

REASON* /PRIORITY**	REFERENCE CODE	DESCRIPTION	COST
H/N		Technical Bridge Inspection	\$500
H/N	36.C	Repair bridge rail post anchorage	\$2,000
H/N	59.C1	Repair bearing devices at abutment #1	\$5,000
H,R/N	59.C2	Paint Steel girders	\$20,000
H/N	60.15	Place riprap along downstream north bank	\$500
H,R,N	61.1	Remove leaning tree	\$500
H/N	Wearing Surface	Asphalt seal and patch on areas above backwalls to stop water from penetrating onto caps	\$400

\*H = Health & Safety  
 \*\*E = Emergency

R = Resource Protection  
 C = Critical

M = Mission  
 N = Non critical

**CONDITION CODES AND REMARKS**

CONDITION RATING			REMARKS	
<b>WEARING SURFACE</b>			<b>G</b>	Some section loss at abutment #1
<b>58. DECK:</b>			<b>7</b>	
*1.	DECK SLAB/PANELS/JOISTS	G	Spalls at guard angles. Transverse cracks in soffit. Crack at railpost connection at abutment #2, upstream.	
C1.	DECK JOINTS	NA		
C2.	CURBS	G	Transverse cracks.	
C3.	SIDEWALKS	NA		
C4.	BRIDGE RAILINGS	G		
C5.	DRAINS AND DRAINAGE	G		
C6.	RIDEABILITY	G		
C7.	CLEANLINESS	G		
C8.	UTILITIES	NA		
<b>59. SUPERSTRUCTURE:</b>			<b>7</b>	
*1.	GIRDERS 5 EA.	F	Weld still cracked at bearing stiffener at abutment #2, exterior girder.	
	A. DIAPHRAGMS	G		
	B. BRACING	NA		
*2.	FLOOR BEAMS	NA		
*3.	STRINGERS	NA		
*4.	TRUSSES	NA		
	A. CHORDS	NA		
	B. PORTALS	NA		
	C. VERTICALS/DIAGONAL	NA		
	D. BRACING	NA		
C1.	BEARING DEVICES	P	Two anchor bolts sheared off at abutment #1, upstream girder.	
C2.	PAINT	F	No noticeable progression in flaking paint on 2 <sup>nd</sup> girder from downstream.	
C3.	DEFLECTION UNDER LOAD	NOB		
C4.	VIBRATION UNDERLOAD	NOB		
<b>60. SUBSTRUCTURE:</b>			<b>7</b>	
A	*1. ALIGNMENT (TIPPING, TILTING,...)	G		
B	*2. EROSION OR SCOUR	F	Loss of material under abutments and end wing walls.	
U	*3. SETTLEMENT	G		
T	<b>TIMBER ABUTMENTS (INCL. WW)</b>			
M	*4. CAPS	NA		
E	*5. POSTS/PILES	NA		
N	*6. BACKING PLANKS	NA		
T	*7. SILLS/FOOTINGS	NA		
S	*8. CRIB WALLS	NA		
	<b>OTHER ABUTMENTS</b>			
	*9. CAPS	G	Random cracking.	
	*10. FOOTINGS	NOB		
	*11. BACKWALLS	G	Leaking joint between backwall and deck causing wet conditions at bearings.	
	*12. PILES	NA	Several tight vertical cracks.	
	*13. WINGWALLS	F	Corner spalls typical.	
P	*14. ALIGNMENT (TIPING, TILTING,...)	NA		
I	*15. EROSION OR SCOUR	NA		
E	*16. SETTLEMENT	NA		
R	*17. CAPS	NA		
S	*18. COLUMNS OR WALLS	NA		
	*19. FOOTINGS	NA		
	*20. PILES	NA		
	*21. BRACING	NA		

\* Only these items are used in the determination of the overall condition rating for that category ie. Deck, superstructure, substructure. Other items should be rated and remarked on but NOT included in determining the overall category rating. Items enumerated using a C (ex C1) should be commented on but not rated. See the FHWA Coding Guide for further information as to what is included in condition rating.

**CONDITION CODES AND REMARKS (Continued)**

CONDITION RATING			REMARKS
<b>61. CHANNEL AND CHANNEL PROTECTION</b>			<b>7</b>
*1.	CHANNEL SCOUR/EROSION	F	As previously noted downstream bank erosion has resulted in undermining of a large tree with exposed roots. Tree is currently leaning towards bridge.
*2.	CHANNEL PROTECTION	G	
*3.	VEGETATION	G	
*4.	WATERWAY OBSTR./DRAFT	G	Log upstream 50'.
*5.	ADEQUACY OF OPENINGS	G	
C1.	CLEAR HEIGHT	G	
<b>APPROACH CONDITION:</b>			<b>G</b>
*1.	SURFACING	G	Loss of surfacing above backwalls.
*2.	SHOULDER EMBANKMENT	G	
*3.	ROADWAY EMBANKMENT	G	
*4.	APPROACH SETTLEMENT	G	Transverse crack at approaches with 1/2" of settlement at abutment #1 (south).
<b>APPRAISAL CODES and REMARKS</b>			
<b>36. TRAFFIC SAFETY FEATURES:</b>		<b>1 1 1 1</b>	
*A.	BRIDGE RAILING	G	Collision impact damage at abutment #2, upstream post at deck connection.
*B.	RAIL TRANSITIONS	G	New 2001.
*C.	APPROACH GUARDRAILS	G	New 2001.
*D.	APPROACH RAIL ENDS	G	New 2001.
1.	SIGNING	NA	
2.	OBJECT MARKERS	G	Located on end buffers.
<b>72. APPROACH ROADWAY ALIGNMENT:</b>			<b>8</b>
1.	HORIZONTAL	G	
2.	VERTICAL	G	
Bridge Appraisal Rating items may change as a result of this inspection. Use FHWA Coding Guide and Regional Office direction for appraisal rating code determination.			
<b>67. STRUCTURAL EVALUATION:</b>		<b>7</b>	<b>68. DECK GEOMETRY:</b> <b>7</b>
<b>71. WATERWAY ADEQUACY:</b>		<b>9</b>	<b>113. SCOUR CRITICAL BRIDGES:</b> <b>6</b>
<b>STRUCTURE LIFE REMAINING</b>		<b>25</b>	<b>SCOUR VULNERABILITY:</b> <b>Not determined</b>

**CONDITION RATING OF EACH MEMBER OR ELEMENT**

- NA -NOT APPLICABLE
- NOB -APPLICABLE, BUT NO OBSERVED. (Give reason unless obvious)
- G = GOOD -ELEMENT IN NEW OR GOOD CONDITION WITH NO REPAIRS NECESSARY.
- F = FAIR -ELEMENT IS STILL PERFORMING THE FUNCTION FOR WHICH IT WAS INTENDED BUT MAY NEED MAINTENANCE.
- P = POOR -ELEMENT STILL PERFORMING THE FUNCTION FOR WHICH IT WAS INTENDED BUT IS IN NEED OF REPAIRS.
- C = CRITICAL -ELEMENT IS NOT PERFORMING THE FUNCTION FOR WHICH IT WAS INTENDED

### INSPECTION PHOTOS



Photo #1 – View of the approach looking back.



Photo #2 – Profile view looking downstream.



Photo #3 – View of the broken anchor bolt at abutment #1.



Photo #4 – View of the expanded bearing at abutment #1. Also note the leaking backwall/deck connection.



Photo #5 – View of material loss typical under both abutments and wing walls.



Photo #6 – View of failing paint on the 2<sup>nd</sup> girder from downstream.



Photo #7 – View of failing approach asphalt at abutment #1 which creates an abrupt transition on to the deck.



Photo #8 – View of the downstream streambank and undermining of a large tree which is leaning towards the bridge.